



# LAKE TREATMENT REPORT

Crosscreek Environmental service summary and site documentation

## Customer & Service Details

**Customer:** Greenacre Property Management      **Job:** 181 - Carrollwood Phase II  
**Date:** 2026-04-09      **Time:** 12:21  
**Technician:** JamesL

## Lakes & Treatments

Lake	Algae	Submersed Weeds	Grasses & Brush	Floating Weeds	Bacteria	Pond Dye	Trash Pickup	Inspection	Water Level	Erosion

## Additional Comments

Followed up on algae on site 5 along with the shorelines of each pond. N9w that water levels are up I'll be boating 2 immediately. I picked up trash during the bulk of my visit. Thank you!

**Project Photos**

**Photo 1**



**Photo 2**



**Project Photos**

**Photo 3**



**Photo 4**



**Project Photos**

**Photo 5**



**Photo 6**



**Project Photos**

**Photo 7**



**Photo 8**



**Project Photos**

**Photo 9**



**Photo 10**



**Project Photos**

**Photo 11**



**Photo 12**



**Project Photos**

**Photo 13**



**Photo 14**



**Project Photos**

**Photo 15**



**Photo 16**



**Project Photos**

**Photo 17**



**Photo 18**



# Project Photos

Photo 19



Photo 20

