



LAKE TREATMENT REPORT

Crosscreek Environmental service summary and site documentation

Customer & Service Details

Customer: Greenacre Property Management **Job:** 181 - Carrollwood Phase II
Date: 2026-06-12 **Time:** —
Technician: JamesL

Lakes & Treatments

Lake	Algae	Submersed Weeds	Grasses & Brush	Floating Weeds	Bacteria	Pond Dye	Trash Pickup	Inspection	Water Level	Erosion
1	X	X	X							
2	X	X	X							
5	X	X	X							
7	X	X	X							

Additional Comments

This report is for my boat visit in Tuesday. I was able to spray all the grasses on the homeowner shoreline in site 7. This site has no access for my atv shoreline sprayer, however the water levels were high enough for me to get in with my boat. I also did several planned eel grass treatments on 5 and 2 along with lots of brown algae.

Project Photos

Photo 1




Photo 2



Project Photos

Photo 3



Photo 4



Project Photos

Photo 5



Photo 6



Project Photos

Photo 7



Photo 8

