



# LAKE TREATMENT REPORT

Crosscreek Environmental service summary and site documentation

## Customer & Service Details

**Customer:** Greenacre Property Management      **Job:** 181 - Carrollwood Phase II  
**Date:** 2026-07-02      **Time:** 13:56  
**Technician:** JamesL

## Lakes & Treatments

Lake	Algae	Submersed Weeds	Grasses & Brush	Floating Weeds	Bacteria	Pond Dye	Trash Pickup	Inspection	Water Level	Erosion
5										
1	X	X	X	X			X			
2	X	X	X	X			X			

## Additional Comments

Spent my afternoon working on pond 1 with the massive bloom then followed up on what I did several weeks ago on the big lake number 2.

## Project Photos

Photo 1



Photo 2



**Project Photos**

**Photo 3**



**Photo 4**



**Project Photos**

**Photo 5**



**Photo 6**

