



LAKE TREATMENT REPORT

Crosscreek Environmental service summary and site documentation

Customer & Service Details

Customer: Greenacre Property Management **Job:** 181 - Carrollwood Phase II
Date: 2026-08-04 **Time:** 13:35
Technician: JamesL

Lakes & Treatments

Lake	Algae	Submersed Weeds	Grasses & Brush	Floating Weeds	Bacteria	Pond Dye	Trash Pickup	Inspection	Water Level	Erosion
1	X	X	X							
2		X	X	X						
5	X	X	X	X						
7	X	X	X	X						
8	X	X	X	X						

Additional Comments

Followed up on several sites with the boat. Site 1 has on going hydrilla treatments, big bloom happened July this is my second application on this site. I hit all the Lilly pads and torpedo grass on 2,5,7 and 8. I also treat algae were needed, water levels are up. Please allow up to seven days for visible results from today's treatments. I'll be following up on site 1 in 2 weeks. Thank you!

Project Photos

Photo 1




Photo 2



Project Photos

Photo 3



Photo 4



Project Photos

Photo 5



Photo 6



Project Photos

Photo 7



Photo 8



Project Photos

Photo 9



Photo 10



Project Photos

Photo 11



Photo 12

